


Precision Clean Multi-purpose Cleaner/Degreaser



FEATURES

- VOC compliant in all 50 states
- Super industrial strength removes tough stains and soils
- Does not contain butyl, chlorinated or petroleum solvents, bleach, ammonia, or abrasives
- Alkaline formula inhibits flash rusting
- Rinses clean
- Safe on all surfaces except magnesium
- Nonfood Compounds Program Listed Category Code: C1 Registration #059854 (Bulk)



APPLICATIONS

- Compressors
- Engines
- Floors
- Food processing equipment
- Hoists
- Lifts
- Printing press
- Tools

iS (IDENTIFICATION SYSTEM)













AVAILABLE PRODUCTS

Part No.	Net Contents	Container	Case Pack	Case Wt.
Ready-to-use				
02720	18 wt. oz. (525 mL)	Aerosol	12	18 lbs.
02728	28 fl.oz. (828 mL)	Trigger	12	27 lbs.
02765	55 gal. (208 L)	Drum	1	535 lbs.
Concentrate				
02701	1 gal. (3.78 L)	Drum	1	38 lbs.
02705	5 gal. (18.93 L)	Pail	1	46 lbs.
02755	55 gal. (208 L)	Drum	1	535 lbs.



Precision Clean Multi-purpose Cleaner/Degreaser

PROPERTIES

Appearance / physical state Liquid
Odor Citrus

PH Aerosol 12.9
RTU 12.5
Concentrate 13.0

Boiling point 212°F (100°C)
Vapor pressure <17.5 mm Hg@20°C

5.8% per State and Federal Consumer Product Regulations

Solubility (water) 100%

Color Greenish-blue Specific gravity 1 - 1.03 @20°C

Vapor density >1

Viscosity <3 cSt Heat of combustion <20 kJ/g

Flammability limits lower 0.7% upper 5.3%

Percent volatile >97%

HANDLING

VOC

Pressurized container: Do not pierce or burn, even after use. Do not use if spray button is missing or defective. Do not spray on a naked flame or any other incandescent material. Do not smoke while using or until sprayed surface is thoroughly dry. Do not cut, weld, solder, drill, grind, or expose containers to heat, flame, sparks, or other sources of ignition. Do not re-use empty containers. Do not breathe gas. Avoid contact with skin. Avoid contact with eyes. Avoid prolonged exposure. Avoid contact with clothing. Use only in well-ventilated areas. Wear appropriate personal protective equipment. Observe good industrial hygiene practices. When using, do not eat, drink or smoke. Wash hands thoroughly after handling.

STORAGE

Store locked up. Pressurized container. Protect from sunlight and do not expose to temperatures exceeding 50°F/122°F. Do not puncture, incinerate or crush. Contents under pressure. Keep away from heat, sparks and open flame. Keep container tightly closed. Store in a cool, dry place out of direct sunlight. Store in a well-ventilated place. Keep in an area equipped with sprinklers. Store away from incompatible materials (see Section 10 of the SDS).

DIRECTIONS

Spray on parts and equipment. Wipe with an absorbent cloth. If equipment is still dirty or greasy, repeat procedure.

DISPOSAL INFORMATION

Waste must be disposed of in accordance with any and all applicable environmental control rules and/or regulations.

